

Integration Guide: Machine Tending with Fanuc CRX

Contents

[Table of Contents](#)



This document provides an overview of the integration and setup for a machine tending robot cell that uses a FANUC CRX cobot. Upon completing the mechanical assembly of your machine tending robot cell, plan between 4-8 hours for the electrical and software configuration prior to production start.

Note that all components that surround the cobot are available on the Vention platform and are delivered as a kit.

Below is a list of topics covered in the integration guide.

Table of Contents

Item	Page
General Overview	3
Mechanical Installation	4
Wiring	7
End-of-arm tool	9
Configuration	12
Install the robot template program	12
Set up robot-to-machine communication	14
Safety setup	16

Verification	17
Calibration & initial programming	20
Additional information	22
Appendix A - Vention 7th Axis	23
Appendix B - Other robot end effectors	24

[Talk to an expert for access to the integration guide](#)